### Application to WEST TISBURY HISTORIC DISTRICT COMMISSION

Instructions: Please type or print. Submit application and exhibits in three complete sets. Add sheets as necessary.

Check type of Certificate applied for:

:

[\*] CERTIFICATE OF APPROPRIATENESS for work as described and exhibits filed.

[\*] CERTIFICATE OF NON-APPLICABILITY for the following reasons:

- [] Not visible from any public street, public way, public park, or public body of water.
- [] Reconstruction similar to original following fire or other disaster.
- [] Maintenance, repair or replacement, using same design, materials, colors.
- [] Proposed work, materials and colors exempted from review by the Commission.
- [v] Meeting requirements certified by authorized public officer to be necessary for public safety because of unsafe condition.
- [] Other.

[] CERTIFICATE OF HARDSHIP for a determination as to whether owing to conditions especially affecting the building or structure involved, but not affecting the historic district generally, failure to approve an application will involve a substantial hardship to the applicant, and as to whether such application may be approved without substantial detriment to the public welfare, and without substantial derogation from the intent of the WTHD By-Law.

LOCATION of work 11 MUSIC STREET	Assessor's Map2 Lot60
OWNERELEVEN MUSIC, LLC	Telephone508-274-2905
ADDRESS PO BOX 3000, PMB 3109, WEST TISBURY, MA	
APPLICANT JOSHUA GOTHARD	Telephone5082742905
ADDRESS_SAME AS ABOVE	
CONTRACTOR HAGERTY TREE	Telephone <sup>508-693-1234</sup>
ADDRESS_2 WING RD, OAK BLUFFS, MA	

#### DESCRIPTION OF ALL PROPOSED EXTERIOR WORK:

REMOVAL OF (4) FOUR NORWAY MAPLE TREES IN VERY CLOSE PROXIMITRY TO AND AT RISK OF CAUSING SUBSTANTIAL DAMAGE TO GUEST HOUSE AND BARN WORKSHOP AT THE REAR OF THE PROPERTY.

LIST EXHIBITS: Drawings, specifications, photographs, materials and colors attached to application.

By\_

- A010 - SITE PLAN

- PHOTOS OF TREE CANOPY FROM MUSIC STREET

- PHOTOS OF TREES IN PROXIMITY TO STRUCTURES

#### CHECKLIST:


 $\checkmark$  site plans showing existing structures and proposed changes

- ✓ photographs of existing conditions
- \_\_\_\_list of materials and /or color samples / catalog cuts
- \_\_\_\_scaled architectural drawings of proposed work if required

Incomplete applications will be returned.

Received by WTHDC: Date\_\_\_\_

Signatures (both are required)	
Jel Sottet	12/26/22
Applicant	Date
lel Still	12/26/22
Owner	Date



# VIEW FROM MUSIC ST.



ED

 $\mathsf{BF}$ 









# Barn/Garage

Garage Type: Garage Size: Door Opener: Detached 1+ Car Manual Opening, Functional but near end of life Condition: Marginal

Opener Safety Feature:


Condition: N/A




Comment 124:

The vegetation growing on and around the barn needs to be cut back significantly. It is negatively impacting the structure in several ways (siding, trim, roofing, insects).





### Figure 124-1



Page 100 of 110



Generally Maintained Condition: Marginal



### Comment 10:

Recommend maintaining all tree, shrub and plant growth trimmed 1-3 feet away from the structure to allow for proper ventilation and help reduce the risk of rot as well as insects using the vegetation as a gateway to the home. See also comments regarding vegetation in the barn/garage section.