CERTIFICATE OF COMPLIANCE SITE VISIT SE79-261 Duarte's Pond and Blackwater Brook Land Bank properties























Causeway and elevated span





End of causeway crossing and 5 earthen stairs.





Side erosion most likely caused by mountain bikers









Start of Blackwater Pond





View platform # 1





Big downed tree





View platform # 2 (noted as 3 on exhibit A.