

Map 35 Lot 1.2
Site Visit
October 6, 2022

Buffer Strip: more than 25 ft but cut low



Required to maintain a 25 ft buffer strip from top of coastal bank



Path to dock from bottom of hill



Dock looking from end





Float stops.



Old path. Area not well vegetated



Example of what buffer strip should look like. This is on this property as well.



Remanents of old pad for dock



Still some erosion on old path

