

99 Pond View Farm Road  
Map 32 Lot 1.9  
Certificate of Compliance  
Site Visit  
April 7, 2022





Grading SE79-394









Area of grading and landscaping






SE79-389 Row of Cedars where invasivise species removal took place





invasive species removal. maybe a little zealous. Good location for boat ramp



Geraldine and the Pussy Willow Tree







Along the first 25 ft of the BZ and the top of bank



04/07/2022





04/07/2022





top of bank



along top of bank





04/07/2022



view created by storm damage according to landscaper



04/07/2022