

Map 15 Lot 1
Site Visit
February 9, 2022



Road left of the boulder is new. May be in the last 10 ft of BZ
Needs to be added to survey.



Brush cut areas and new road. Need to know if this is in the BZ



Orange is wetland flag B5. Boulders appear to mark sides of a road



Clear indication of alteration that has been covered with top soil, woodchips and branches. Filter fabric can be seen.



Road area and exposed filter fabric



More examples of alteration. Need these areas shown on the site plan to determine whether they are within BZ



Photo on left is looking toward Indian Hill Road. Need to know if area to the right is within BZ. Same with area shown on photo on the right.



Grading rake in the woods. New road along stone wall at the back of the lot on the south end of the property. Abutting Map 15 Lot 24.



Photo on left is looking to abutter's property. Not sure if they are the ones that took the videos.



New alteration along the southern boundary line. Need to know if this is within the BZ.



Taken from the new area of alteration towards the garden and woodchipped area shown on the 8/2020 plan