

SITE VISIT
CAPAWOCK AND OAK GROVE ROAD
REMOVAL OF UTILITY POLES







This pole is in the wetland. We did not walk to the other side to see where the line will go under the stream. Too wooded to walk through this way.



wetland vegetation.



wetland vegetation



wetland vegetation