

Map 43 Lot 1
100 Watcha Club Road
Site visit for view channels
October 18, 2023

Limit of work is the fencing




View channel is staked



Talked about taking out trees on the inland side of the limit of work first



then flagging trees to be removed on the water side of this fence.



Leach field



View from the main house

